



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	David Shaver Manager				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070019				
Inspection Type:	PARTIAL				
Inspection Date:	Thursday, December 10, 2009				
Start Date/Time:	12/10/2009 9:00:00 AM				
End Date/Time:	12/10/2009 11:00:00 AM				
Last Inspection:	Thursday, November 19, 2009				

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 4 Deg. F. InspectionID Report Number: 2216

Accepted by: jhelfric

12/28/2009

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: CENTENNIAL MINE

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,528.83	Total Permitted Total Disturbed		
47.19			
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

✓ Federal

Other

Types of Operations ✓ Underground

Reprocessing

✓ State Surface County Loadout **✓** Fee Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Thursday, December 10, 2009

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070019

Inspection Type: PARTIAL Inspection Date: Thursday, December 10, 2009 **Inspection Continuation Sheet**

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.					
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	V		V	

Inspection Continuation Sheet

Permit Number: C0070019

Inspection Type: PARTIAL

Inspection Date: Thursday, December 10, 2009

Page 3 of 3

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.a Hydrologic Balance: Diversions

Diversons snow covered.

22. Other

Area is snow covered. Mine site remains idle.